

Ecology Team Consultation Response

Hi Sarah,

Can you please forward the attached photos to the Ecology Team. Along with these comments;

There is no loft void to the existing building, the roof space being open internally to the existing second floor.

Furthermore, the roof finish to the existing building is in a good state of repair, with close fitting tiles. There is no opportunity for bat roosting within the Tile-Felt void.

Finally, during the ongoing site works no evidence of bat roosting has been observed.

We therefore do not consider a PRA to be necessary in this instance. Will the Ecology Team please confirm that they are in agreement?

Many Thanks

Spencer Fretwell



