

Unit 2, Mereside Greenbank Road Eden Business Park Gilwilly, Penrith Cumbria, CA11 9FB

PROPOSED NEW HOUSING DEVELOPMENT MORESBY PARKS – CUMBRIA 4TH JULY 2022

OPERATION AND MAINTENANCE PLAN SURFACE WATER DRAINAGE SYSTEM

4th July, 2022

DIRECTORS

E. Slater BSc (Hons) CEng MIStructE
S. C. Mair BSc (Hons) CEng MIStructE MICE
R. J. Gibson BEng (Hons) CEng MIStructE

Tel 01768 865400 Fax 01768 865002
Email mail@tsce.uk.com
www.tsce.uk.com

1. INTRODUCTION

It is proposed that the entire surface water system on site will be adopted by United Utilities (UU) therefore will be under the maintenance of UU. This will include the actual detention basin.

Volume Control

The detention basin has been designed such that it will not be surcharged in events up to 100 years recurrence. The discharge rate is to be restricted by a Hydro brake controlling the discharge rate to 8.1 l/s.

Structural Integrity

The proposed surface water drainage systems has been designed to Building Regulations to ensure the structural integrity under the anticipated loading conditions over the design life. This includes the cover to pipes that has been designed in accordance with the manufacture's requirements and specification.

2.0 GENERAL DRAINAGE SYSTEM

MAINTENANCE SCHEDULE	REQUIRED ACTION	RECOMMENDED FREQUENCY
Ongoing Monitoring United Utilities	Inspect/check all upstream drainage inlets, outlets, vents and gullies to ensure that they are in good condition and operating as designed.	Annually and after large storm events
Remedial Actions United Utilities	Repair/rehabilitation of inlets, outlets, overflows and vents. Removal of oil and grease. Replacement of malfunctioning parts.	As required

3.0 DETENTION BASIN

MAINTENANCE SCHEDULE	REQUIRED ACTION	RECOMMENDED FREQUENCY
Ongoing Monitoring /Maintenance Basin United Utilities	Inspect and identify any areas upstream and downstream of the basin that are not operating correctly (i.e. road gullies, interceptor, filter drains). If required, take remedial action.	Monthly for first three months, then six monthly thereafter.
	Remove debris from basin (may cause risks to performance).	Monthly for first three months, then six monthly thereafter (and after large storm events).

Operation and Maintenance Plan – Moresby Park - Cumbria

Page No. 3

MAINTENANCE SCHEDULE	REQUIRED ACTION	RECOMMENDED FREQUENCY
	Visual inspection of basin, De-silt as required. A maintenance track will be installed right around the pond. Excavator to be used to remove sediment with care not to damage the base of the pond. Access via maintenance strip and 1 in 4 side slopes.	Monthly for first three months, then six monthly thereafter (and after large storm events).
	Remove sediment from interceptor, chambers, road gullies and jet associated pipework.	Annually, or as required.

4.0 HYDRO BRAKE CHAMBER

MAINTENANCE SCHEDULE	REQUIRED ACTION	RECOMMENDED FREQUENCY
Ongoing Monitoring/Maintenance – Hydro Brake Chamber United Utilities	The hydro brake control is to be applied by Hydro International and their recommendations for maintenance are appended to this report. Ongoing monitoring to inspect chamber for blockages.	Inspect monthly for 3 months and thereafter at 6 monthly intervals.
Ongoing Monitoring General Drainage System United Utilities	Inspect/check all upstream drainage inlets, outlets, vents and gullies to ensure that they are in good condition and operating as designed.	Annually and after large storm events
Remedial Actions United Utilities	Repair/rehabilitation of inlets, outlets, overflows and vents. Removal of oil and grease. Replacement of malfunctioning parts.	As required

5.0 DIVERTED SURFACE WATER CULVERT

As shown on drawing 6972_202M the length of the diverted surface water culvert with the highway boundary of School Brow will be maintained by Cumbria County Council (CCC) The rest of the diverted surface water culvert will be maintained by the private management company.

MAINTENANCE SCHEDULE	REQUIRED ACTION	RECOMMENDED FREQUENCY
Ongoing Monitoring CCC & private management company.	Inspect/check all upstream drainage inlets, outlets, vents and gullies to ensure that they are in good condition and operating as designed.	Annually and after large storm events
Remedial Actions CCC & private management company.	Repair/rehabilitation of pipework and inspection chambers.	As required

Tweddell & Slater Ltd Unit 2 Mereside Greenbank Road Eden Business Park Penrith Cumbria CA11 9FB AKP July 2022