

## PLOT A INVESTIGATION PHOTOGRAPHS

### General



Photo 1 - View from TP601A looking southwest over the former Cathedral Area



Photo 2 - View from TP615A looking southwest over former Plant Area





Photo 3 - View from WS503A looking southwest over former Fatty Alcohol Plant

#### **Trial pitting**



Photo 4 - TP607A – located in Cathedral Area, reinforced concrete and hardcore overlying Fill Material





Photo 5 - TP615A – located in Plant Area, contaminated Fill Material between concrete foundations



Photo 6 - TP616A –located in Plant Area, deep concrete foundations present at 1.0m bgl





Photo 7 - TP622A – located in vicinity of former electrical substation, loose Fill Material



Photo 8 - TP628A – located in former Fatty Alcohol Plant, contaminated water running into trial pit through gravel Made Ground





Photo 9 - TP630A – located in former Fatty Alcohol Plant, trial pit excavated into natural ground (Boulder Clay drift: firm red brown silt)