

5/17/2021

20210311_104305_resized_1.jpg

①

Photograph of Poor
Condition of Cornicing
to downstairs ground
floor dining room (front room)
before further investigation
works



<https://mail.google.com/mail/u/0/#inbox/FMfcgxwLttGdrfdmBVKnRjzrRTCSzdK?projector=1&messagePartId=0.1>



(2) -

Further Investigation into
Condition of Joists. After
Consultation with Tom Short.

③.



Photograph of
First floor Corning Condition.

Also showing Poor Condition
of Walls, before any

Investigations.


(4)



Evidence of small
hole in wall

where you can see
lath & Plaster.

NO Investigation Works
needed.



(5) .

Photograph of typical
wall that has Plaster
board - to all main
areas and most bedrooms.