

Typical Car Park Detail



Typical Paving Detail



Typical Retaining Wall Detail



Typical Inspection Chamber
Sited in hard landscaped areas
with standard round cover



Typical Inspection Chamber
Sited in soft landscaped areas
with standard round cover



Typical Back Inlet Gulley Detail



Typical Rodding Eye Detail

General Notes:

All work undertaken in accordance with sewers for adoption 6th edition "A Design & Construction Guide For Developers"

Notes.

Rev.	Date.	Notes.	Init.

Client/Project.
CGP Limited
Civil/Structural/Architectural Design - Office & Cafeteria Extension - Phase 3 @
Mainsgate Road
Millom, Cumbria, LA18 4JZ

Drawing Title.
ROAD LEVELS

Status.
TENDER

Date.	Drawn.	Scale.
06/01/2021	RB	1:10 - A1

Drawing No.	Revision.
20198-PL-C004	

M & P Gadsden
Consulting Engineers Ltd
Unit 20
Meetings Industrial Estate
Park Road
Barrow-in-Furness
Cumbria
Tel: 01229 813333
Web: www.mpg-consulting.co.uk