


Sections Scale 1:500


Datum 125.0

Station	Survey 1 levels	Survey 2 levels
132.099	132.099	132.099
131.994	131.994	131.994
131.783	131.783	131.783
131.781	131.781	131.781
131.566	131.566	131.566
131.470	131.470	131.470
131.600	131.600	131.600
131.493	131.493	131.493
131.301	131.301	131.301
131.321	131.321	131.321
131.356	131.356	131.356
131.328	131.328	131.328
131.160	131.160	131.160
131.125	131.125	131.125
131.081	131.081	131.081
131.050	131.050	131.050
132.000	132.000	132.000
132.441	132.441	132.441
132.000	132.000	132.000
131.500	131.500	131.500
131.290	131.290	131.290
131.000	131.000	131.000
130.965	130.965	130.965
130.957	130.957	130.957
130.970	130.970	130.970
131.294	131.294	131.294
131.255	131.255	131.255
131.301	131.301	131.301
131.123	131.123	131.123
130.932	130.932	130.932
130.917	130.917	130.917
130.855	130.855	130.855
131.075	131.075	131.075
131.121	131.121	131.121
132.309	132.309	132.309
132.499	132.499	132.499
132.276	132.276	132.276
132.301	132.301	132.301
132.288	132.288	132.288
132.240	132.240	132.240
132.255	132.255	132.255
132.257	132.257	132.257
131.365	131.365	131.365
130.569	130.569	130.569
130.534	130.534	130.534
130.401	130.401	130.401


Section H Chainage 350.0m (299382.3E 517898.0N)



Section G Chainage 300.0m (299334.3E 517912.1N)



Section F Chainage 250.0m (299286.3E 517926.2N)



Section E Chainage 200.0m (299238.4E 517940.3N)



Section Location Plan Scale 1:2000

IMPORTANT NOTE:
 Height of Pylon Cables are unknown.
 Mounds under cables may need to be reduced in height on site to comply with minimum clearance requirements in accordance with ENWL guidelines

The map shows a proposed cable route (red line) and section locations (A through J) for a project. The route starts at the bottom left, goes up through a series of mounds and ponds, and ends at the top right. Section locations are marked with red lines and labels: 0m A, 50m B, 100m C, 150m D, 250m F, 300m G, 350m H, and 400m J. The map includes contour lines, a river, and various buildings. A yellow warning triangle with an exclamation mark is in the top right corner.

IMPORTANT NOTE:
Height of Pylon Cables are unknown.
Mounds under cables may need to be reduced in height on site to comply with minimum clearance requirements in accordance with ENWL guidelines

