

Buzz Station - Culvert Repairs

SKDS commenced work on the culvert repairs on the 19/10/2020 and was completed on the 20/10/2020. Entry was made into the culvert under a Confined Space Entry permit.

All major defects were repaired by using stone retrieved from the culvert. These were held in place with a CT-6 compound.

The following pictures show the condition and repairs. Due to the size of the stone/boulders in the culvert a camera could not travel.



The culvert has a constant flow and is restrictive in size.





Stone retrieved from the culvert being used for repairing



VAT Reference - 300430083
S K Drainage Solutions Ltd registered number - 11360332




point up joints.

CT-6 Used to fix stone into place and




VAT Reference - 300430083

S K Drainage Solutions Ltd registered number - 11360332




The walls and arch have been pointed.

If you require any further information, please do not hesitate in contacting me.
Thank you,



Stephen Oakes



VAT Reference - 300430083
S K Drainage Solutions Ltd registered number - 11360332