

- C20/120
  Dismantle parapet wall and outer leaf
  brickwork to top of ground floor windows
- 2 C20/120 Remove existing walkway membrane
- 3 F30/180 Install 15 mm cavity closer
- 4 F10/255
  Rebuild inner leaf of parapet wall with concrete facing blockwork 7.3 N/mm² in stretcher bond
- 5 F30/455 Remove and reinstall existing coping stones
- 6 F30/345 Install site formed cavity trays
- 7 F30/105 Install precast concrete lintel
- 8 S31/110
  Apply new liquid applied waterproof coating to first floor external access walkway and inner leaf parapet \_\_\_\_\_
- 9 F10/110
  Rebuild outer leaf brickwork from above structural openings to top or parapet wall with brickwork to match existing or approved by planning/ conservation officer including solider courses
- 9A F10/110
  Solider course bond band diving ground and first floors
- 9B F10/110 Solider Course above structural opening
- 10 F30/131
  Weep holes at 1000 mm centres
- 11 F30/455 Remove and reinstall existing coping stones
- 12 F30/220
  Stainless steel wall ties at 450 mm vertical and 900 mm horizontal centres —

## © RNJ Partnership

## Notes

Do not scale, use figured dimensions only.

All dimensions to be verified on site prior to the commencement of any works. Any discrepancies should be reported to RNJ Partnership LLP.

Scale 1:5 @ A3 0mm 50mm 100mm 150mm 200mm 250mm

A 15.11.23 Omit: rough cast render
Add: Rebuild outer leaf of
brickwork to top of structural
openings and parapet wall

REV. DATE DESCRIPTION



Chartered Quantity Surveyors Chartered Building Surveyors Project Managers Principal Designers Asbestos Surveyors

2 DIAMOND COURT KENTON NEWCASTLE UPON TYNE NE3 2EN Tel. 0191 286 0707 Fax. 0191 286 0865

email : rnj@rnjllp.com

HOME GROUP

DUKE STREET WHITEHAVEN

REPAIRS TO WALKWAY PARAPET

 DRAWN
 LCJ
 CHECKED RT

 SCALE
 1:5

 ② A3

 DATE
 JUNE
 23

Drg.No. BS/23/11/03

REV. A