

Ref. - Erect Granny Platannex + Garage Rockland extension Lady Hall Herons Reach. Millom Green Road The Green Cumbria LA18 5HR Millom . Cumbria LAIS 5JA 11-05-2023 Flood risk assessment Enclosed : (showing nam features mentioned later in the assessment) · copy of O.S. map, scale 1:2500, showing : A) Position of proposed extension/annex, + boundares ... identified REO B) as levels, located on highway running parallel to Beck, PINK c) Black Beck, adjarcente ORANGE D) Access to site, via bidge over Black Bede YELLOW · Copy of COV. UK plood maps showing :-A Risk of flooding from surface water is very LOND. " Rivers - Sea is MEDIUM. · F) Block plan showing existing & proposed levels. Scale 1:100 1) As stated in Gou. VK flood map the risk of flooding from sinface water is very Low around the site in general. 2) There is a risk of plooding from the adjorent "Black Beck (c) if it burst its banks, but no risk from tidal flooding as the O.S. map shows the 8.5 m AOD on the highway to the north (B) which is well above the "I IN 200 year indefended modelled flat calm tidal flood level of 7.0 AOD for the year 2115" (EA. data) Other readings of 11.6 +7.3 show the general fall of the highway + Black Bede", 3) Access to the site from the highway is up a ramp or over a bridge which spans the Black Beck " Then a gradual slope down to the existing garage anea. if the block plan (F) shows all the ground levels, offour levels of the existing & proposed buildings, along with the base of Black Beak" This shows the existing Heizne Reach place is 1500(1.5m) above the beck where shown, + with a low wall to the beck edge between. The ground falls away to an existing garage which has a floor level of -710mm below the bungalow floor. To the east of the proposed, the ground drops to -1140 mm, where an old hedge line was located. 5) In order to provide draunage from the proposed annex to the existing septic tank, ground cover to same, + min isom to damp proof coarse" the Annex ploar level will be identical to the existing bungalow The garage extension will be same floor level as the existing at -710 mm 6) because the ground around Herons Reach Palls away to the south & east, any flood water fram Black Beak' would run in that direction to lower ground. It is highly in tikky There will be flood water actually entering the annex.

- 7) to intrigate damage to electrical works, all sockets a switches in the annex are to be located between 450+1200 above ploor level, as per building reg's requirement, a all same to be located at 200m high within the garages. (As per Note 4 on plan N° 1770 sheet i) a wined top down.
 - 3) The storage of oils, paints, pesticides a other contaminates to be stored on shelves above bench hight in the garages.
 - 9) Flood boards to be made, a stared for use in the event of plooding for the 2 garage door openings.





View the flood risk information for the location you originally searched for (/risk)

View the flood risk information for another location (/postcode)



Contains OS data © Crown copyright and database rights 2023

Extent of flooding from rivers or the sea

<u>High</u>

Medium

Low

<u>Very low</u>

Location you selected

View the flood risk information for the location you originally searched for (/risk)

View the flood risk information for another location (/postcode)

