


Internal Elevation A
(Existing)



Internal Elevation B
(Existing)

The existing organ
is currently in a state
of disrepair with parts
missing.



NR Design Services Ltd
30 Salterbeck Terrace, Workington, Cumbria,
CA145HP
Email: nathan-routledge@live.com
Tel: 01946 831280
Mob: 07568 179916
Notes:

CLIENT:				Hui Wang			
SITE:				St Johns Church Cleator Moor Cumbria CA25 5BY			
TITLE: Existing Internal Elevations							
SCALE AT A3:	DATE:	DRAWN:					
1:50	06/08/21	NR					
PROJECT NO:	DRAWING NO:	REVISION:					
0821-003	009	A					