



No 1

Photograph looking south across the eastern entrance to area F2 from Harras Road.



No 2

Photograph looking west across area F2 from the eastern entrance.



No 3

Photograph looking west from Harras Road across area F4



No 4

Photograph looking south from Harras road across area F4 showing the small field separated by a low bund of trees.



No 5 | Photograph looking south from area F2 into area F3



No 6 | Photograph looking north west along broken fence boundary between area F2 and area F1.



No 7	Photograph looking west across the former dry stone wall field boundary between area F2 and F1.
------	---



No 8	Photograph looking south west downhill across area F1
------	---



No 9

Photograph looking north east along northern site boundary in area F1 showing the potential watercourse along the boundary, noted as a saturated length long grasses.



No 10

Photograph looking north east from Loop Road South from western site entrance to area F1.



No 11

Photograph looking south west across area F1 showing the cattle water trough potentially filling from shallow soil drainage.



No 12

Photograph looking south showing entrance to the playing fields area in area F7.



No 13 Photograph looking south east across the playing field area in area F7.



No 14 Photograph looking east from the playing field area of area F7 towards a site entrance from Red Lonning (road)