



No 15

Photograph looking west into the wooded area in area F7



No 16

Photograph looking north west across the turning circle for the access road to the site from the south.





No 17

Photograph looking east across the southern field of area F8



No 18

Photograph looking east across the area to the south of the southern field in area F8 showing heavy waterlogging and log grasses.





No 19

Photograph looking north east across the northern field of area F8.



No 20

Photograph looking west across area F9.





No 21 | Photograph looking south east along the track between area F5 (left) and F8 (right).



No 22 | Photograph looking north from the track to the mound adjacent to the turning circle.





No 23

Photograph looking south across the northern field in area F8 towards the mound along the access road.



No 24

Photograph looking north west across area F5.





No 25

Photograph looking west along the track between the northern and southern fields of area F6.



No 26

Photograph looking north across the northern field of area F6.





No 27

Photograph looking south across the southern field of area F6 with the small stables on the far left.



No 28

Photograph looking south along the rough area of drainage channels west of the fields in F6.