



Photograph No: 1 Area of oil spill as shown by surface staining, April 2008



Photograph No: 2 Location of CHP scrape, June 08





Photograph No: 3 CHP scrape in progress, June 08



Photograph No: 4 CHP scrape in progress showing concrete hardstanding in good condition, June 08