

PLOT C INVESTIGATION PLATES



Plate 1 – View over Plot C towards northeast with S4 Building in the background.



Plate 2 – Area of potential arsenic contamination- View east.



Plate 3 – View towards west with Hutbank landfill in the background.



Plate 4 – TP118C (0.1m).



Plate 5 – TP118C (0.5m) Red-brown topsoil followed by grey-brown clayey soil with metal, bricks, and occasional red clay.



Plate 6 – TP119C (0.5m)



Plate 7 – TP119C (1m)



Plate 8 – TP120C (1m)