

KW 2



View from Footpath showing how close the tree is to the path and adjacent property.



View from footpath showing the weakened area of trunk.



2nd view from footpath.



View from Gardens showing area of rot and hole to the cavity.