

### Window Legend to be used with the supplied photographs

#### Numbers 1 -18 (replacement windows)

Approximately 440mm x 440mm – white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

#### Numbers 19-27 (replacement windows)

Approximately 485mm x 830mm – white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

#### Numbers 28-36 (replacement windows)

Approximately 485mm x 830mm – white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handle.

#### Number 37 (not replaced)

Approximately 320mm x 330mm – white painted timber, single glazed, significant decay of the frame, needs to be replaced asap.

#### Numbers 38-42 (not replaced)

Approximately 880mm x 1420mm – white painted Georgian sash windows, single glazed, some decay beginning to show to the frames.

#### Number 43 (replacement window)

Approximately 920mm x 890mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handle.

#### Number 44 (replacement window)

Approximately 440mm x 760mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

#### Number 45 (replacement window)

Approximately 900mm x 1200mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

#### Number 46 (replacement window)

Approximately 360mm x 600mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

#### Number 47 (replacement window)

Approximately 690mm x 580mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handles.

#### Number 48 (replacement window)

Approximately 390mm x 620mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 49 (replacement window)

Approximately 350mm x 670mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 50 (replacement window)

Approximately 350mm x 670mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 51 (replacement window)

Approximately 820mm x 730mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 52 (replacement window)

Approximately 380mm x 680mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 53 (replacement window)

Approximately 470mm x 410mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 54 (replacement window)

Approximately 1040mm x 880mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handle.

Number 55 (replacement window)

Approximately 1070mm x 920mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handle.

Number 56 (replacement window)

Approximately 375mm x 670mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handle.

Number 57 (replacement window)

Approximately 440mm x 760mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handle.

Number 58 (replacement window)

Approximately 440mm x 760mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 59 (replacement window)

Approximately 900mm x 1200mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handles.

Number 60 (replacement window)

Approximately 330mm x 330mm - white painted timber, 14mm heritage sealed unit, white spacer, non-opening.

Number 61 (replacement window)

Approximately 870mm 1050mm - white painted timber, 14mm heritage sealed unit, white spacer, opening window with black cast iron monkey tail handles.

Number 62 (window not replaced)

Approximately 485mm x 600mm – Leaded window (non-opening), comprising rectangles of green and yellow coloured glass set in a timber white painted frame. The timber frame shows signs of decay and will need to be replaced in the next few years. The window is unlikely to be original, it looks more like a 20<sup>th</sup> Century replacement using coloured rather than painted glass.