

APPENDIX C

DESIGNERS EXCEPTION REPORT

CROSSINGS CLOSE

CLEATOR MOOR

ITEM	DESIGNERS RESPONSE
7.1	This is an Existing Pedestrian access with long established use. As noted in the report there are no records of any incidents.
	Crossings Close and the Verge next to the site entrance are not adopted.
	Earlier consultation with Highways has determined that maintaining the site entrance As Existing, is an appropriate design solution.
7.2	Similar to the above, this is an Existing Vehicle access with long established use. As noted in the report there are no records of any incidents.
	As noted in the report there are no records or any incidents.
	Earlier consultation with Highways has determined that maintaining the site entrance As Existing, is an appropriate design solution.
7.3	
	Swept Path Analysis attached, showing the design to be suitable for all vehicles and the radius bend to be
	satisfactory.
7.4	
	The proposals are likely to see Reduced Pedestrian movement from the site onto
	Whitehaven road, compared to when the Chapel was in full use.